



3.11 #11, INDUSTRIAL WASTE MATERIALS MANAGEMENT

Location: The Industrial Waste Materials Management landfill is owned by a commercial

entity, and is located in northeast Austin, at Hwy 290 and Giles Road. The Industrial Waste Materials Management landfill appears today essentially as

described in the 1984 URM report.

Extent: The closed landfill site is situated within an active landfill and near several other

active and closed commercial landfills. The landfill is evident as a raised cap and is well graded with a grass cover. No trees or brush are growing on the landfill

surface. The site is fenced to restrict public access.

Prior Use: no information available

Groundwater: This closed site is monitored by Waste Management Inc. under an agreement

with the City of Austin that requires groundwater monitoring and periodic inspection of the adjacent creek bank for seeps and erosion. The surrounding active landfill (WMI, Austin Community Disposal Landfill) operates a leachate

collection system and a soil gas venting system.

Remediation: see above

Current Conditions: Beyond those conditions already being addressed by Waste Management Inc., current conditions associated with this site do not appear to pose a material concern to human health or the environment, or represent a regulatory violation.

Reference: Information in this fact sheet comes from the following:

- 1. Geomatrix Consultants. November 2004. 2004 Supplemental Assessment to Landfills in the Vicinity of Austin, TX. Prepared for City of Austin Public Works Department.
- 2. Underground Resource Management, Inc. November 1984. *Landfills in the Vicinity of Austin, TX.* Prepared for the City of Austin.